

READY TO RESUME
NOZZLE HEATING
LOADING FILAMENT
NOZZLE COOLING
WIPING
MOVING TO WIPE
IDLE
None
Filament
filament out
0
20
40
60
80
100
120
140
160
180
200
time [s]