

Printer machine
PAUSED
FAILED
COMPLETED
IN PROGRESS
IDLE
None
Filament machine
READY TO RESUME
NOZZLE HEATING
LOADING FILAMENT
NOZZLE COOLING
WIPING
MOVING TO WIPE
IDLE
None
Nozzle machine
Cooling
too hot
cooled but not supposed to
Heated
HeatingUp
Cool
None
L_{max}
C
L [m]
15
10
5
0
0
20
40
60
80
100
120
140
160
180
200
time [s]