
READY TO RESUME
NOZZLE HEATING
LOADING FILAMENT
NOZZLE COOLING
WIPING
MOVING TO WIPE
IDLE
None
Filament
filament out
C
0
50
100
150
200
250
300
350
400
time [s]