
IDLE
IN PROGRESS
START==1
WAIT HOT
heated
TRAVEL TO START
hasChangedTo(PAUSE_RESUME, 1)
‖ hasChangedTo(C, 1) ‖ F
PAUSED
(hasChangedTo(PAUSE_RESUME,
1) ‖ change_done) &&
~change_active
at_wall
duration(arrived) > 0.5 &&
~failed
PRINT PATH
k < p.n_path && arrived
k == p.n_path &&
duration(arrived) > 0.5
COMPLETED
at_wall
duration(arrived) > 0.5 &&
~failed
FAILED