

ERROR MEMORY REPORT

Date: 09/08/26 11:10:15
ECU: MS430DS0
JobStatus: OKAY
Variant: MS430DS0

RESULT: 9 errors in error memory !

37 Switching delay main relais

Error frequency : 1
Logistic counter: 40

VB	0.10 V
V_IGK	5.10 V
TCO	20.25 Grad C
N_32	0.00 rpm
aufgetreten vor (rel. BZ)	87.50 h

main relais switched not / delayed

Error debounce
Error currently available
stat. Error

Errorcode: 25 61 01 28 01 32 5B 00 B7 F6

227 lambda contol tolerance Bank 1

Error frequency : 182
Logistic counter: 40

N_32	672.00 rpm
MAF	70.81 mg/stk
TCO	96.75 Grad C
LAM_MV_1	10.93 %
aufgetreten vor (rel. BZ)	83.50 h

Deviation rich

Error to relevant
Error debounce
Error currently available
sporadic Error

Errorcode: E3 F1 B6 28 15 0D C1 9C B8 1E

239 burning fail Cylinder 2

Error frequency : 62
Logistic counter: 32

TCO	18.75 Grad C
-----	--------------

N_32_TOL	1056.00 rpm
MAF_TOL	266.91 mg/stk
MAF_BOL	103.49 mg/stk
aufgetreten vor (rel. BZ)	49.10 h

Misfire CARB_A
Misfire CARB_B1
Misfire CARB_B4

Error to relevant
Error debounce
Error currently not available
sporadic Error

Errorcode: EF B7 3E 20 59 21 31 13 B9 76

228 lambda contol tolerance Bank 2

Error frequency : 172
Logistic counter: 40

N_32	672.00 rpm
MAF	76.26 mg/stk
TCO	34.50 Grad C
LAM_MV_2	-0.00 %
aufgetreten vor (rel. BZ)	49.10 h

Deviation rich

Error to relevant
Error debounce
Error currently available
sporadic Error

Errorcode: E4 F1 AC 28 15 0E 6E 80 B9 76

238 burning fail Cylinder 1

Error frequency : 45
Logistic counter: 32

TCO	61.50 Grad C
N_32_TOL	704.00 rpm
MAF_TOL	168.86 mg/stk
MAF_BOL	157.96 mg/stk
aufgetreten vor (rel. BZ)	48.90 h

Misfire CARB_B1
Misfire CARB_B4

Error to relevant
Error debounce
Error currently not available
sporadic Error

Errorcode: EE B6 2D 20 92 16 1F 1D B9 78

240 burning fail Cylinder 3

Error frequency : 64
Logistic counter: 32

TCO	61.50 Grad C
N_32_TOL	704.00 rpm
MAF_TOL	168.86 mg/stk
MAF_BOL	157.96 mg/stk
aufgetreten vor (rel. BZ)	48.90 h

Misfire CARB_A
Misfire CARB_B1
Misfire CARB_B4

Error to relevant
Error debounce
Error currently not available
sporadic Error

Errorcode: F0 B7 40 20 92 16 1F 1D B9 78

242 burning fail Cylinder 5

Error frequency : 33
Logistic counter: 29

TCO	67.50 Grad C
N_32_TOL	704.00 rpm
MAF_TOL	168.86 mg/stk
MAF_BOL	157.96 mg/stk
aufgetreten vor (rel. BZ)	48.80 h

Misfire CARB_A
Misfire CARB_B1
Misfire CARB_B4

Error to relevant
Error debounce
Error currently not available
sporadic Error

Errorcode: F2 B7 21 1D 9A 16 1F 1D B9 79

241 burning fail Cylinder 4

Error frequency : 22
Logistic counter: 29

TCO	58.50 Grad C
N_32_TOL	800.00 rpm
MAF_TOL	130.73 mg/stk
MAF_BOL	98.05 mg/stk
aufgetreten vor (rel. BZ)	46.50 h

Misfire CARB_B1
Misfire CARB_B4

Error to relevant
Error debounce
Error currently not available
sporadic Error

Errorcode: F1 B6 16 1D 8E 19 18 12 B9 90

243 burning fail Cylinder 6

Error frequency : 1
Logistic counter: 27

TCO	96.75 Grad C
N_32_TOL	896.00 rpm
MAF_TOL	196.09 mg/stk
MAF_BOL	108.94 mg/stk
aufgetreten vor (rel. BZ)	5.40 h

Misfire CARB_B1

Error to relevant
Error debounce
Error currently not available
sporadic Error

Errorcode: F3 B2 01 1B C1 1C 24 14 BB 2B

=====