

ERROR MEMORY REPORT

Date: 09/09/26 10:39:31
ECU: MS430DS0
JobStatus: OKAY
Variant: MS430DS0

RESULT: 7 errors in error memory !

238 burning fail Cylinder 1

Error frequency : 2
Logistic counter: 31

TCO	31.50 Grad C
N_32_TOL	1312.00 rpm
MAF_TOL	294.14 mg/stk
MAF_BOL	157.96 mg/stk
aufgetreten vor (rel. BZ)	5.40 h

Misfire CARB_B1

Error to relevant
Error debounce
Error currently not available
sporadic Error

Errorcode: EE B2 02 1F 6A 29 36 1D 6A A4

242 burning fail Cylinder 5

Error frequency : 1
Logistic counter: 30

TCO	31.50 Grad C
N_32_TOL	1312.00 rpm
MAF_TOL	294.14 mg/stk
MAF_BOL	157.96 mg/stk
aufgetreten vor (rel. BZ)	5.40 h

Misfire CARB_B1

Error to relevant
Error debounce
Error currently not available
sporadic Error

Errorcode: F2 B2 01 1E 6A 29 36 1D 6A A4

240 burning fail Cylinder 3

Error frequency : 1
Logistic counter: 30

TCO	31.50 Grad C
-----	--------------

N_32_TOL	1312.00 rpm
MAF_TOL	294.14 mg/stk
MAF_BOL	157.96 mg/stk
aufgetreten vor (rel. BZ)	5.40 h

Misfire CARB_B1

Error to relevant
Error debounce
Error currently not available
sporadic Error

Errorcode: F0 B2 01 1E 6A 29 36 1D 6A A4

243 burning fail Cylinder 6

Error frequency : 1
Logistic counter: 30

TCO	31.50 Grad C
N_32_TOL	1312.00 rpm
MAF_TOL	294.14 mg/stk
MAF_BOL	157.96 mg/stk
aufgetreten vor (rel. BZ)	5.40 h

Misfire CARB_B1

Error to relevant
Error debounce
Error currently not available
sporadic Error

Errorcode: F3 B2 01 1E 6A 29 36 1D 6A A4

241 burning fail Cylinder 4

Error frequency : 1
Logistic counter: 31

TCO	39.75 Grad C
N_32_TOL	1408.00 rpm
MAF_TOL	315.93 mg/stk
MAF_BOL	174.31 mg/stk
aufgetreten vor (rel. BZ)	4.30 h

Misfire CARB_B1

Error to relevant
Error debounce
Error currently not available
sporadic Error

Errorcode: F1 B2 01 1F 75 2C 3A 20 6A AF

214 Tacho signal unplausible

Error frequency : 10
Logistic counter: 40

N_32	2592.00 rpm
MAF	392.19 mg/stk
GEAR_SEL_DISP	5.00 -
VB	13.77 V
aufgetreten vor (rel. BZ)	3.00 h

Signals not plausible

Error debounce

Error currently not available

sporadic Error

Errorcode: D6 B8 0A 28 51 48 05 87 6A BC

204 idle speed

Error frequency : 1
Logistic counter: 40

N_32	1056.00 rpm
THR	3.91 Grad TPS
ISAPWM	6.27 %
MAF	38.13 mg/stk
aufgetreten vor (rel. BZ)	0.20 h

LL-engine-speed Deviation

Error to relevant

Error debounce

Error currently not available

sporadic Error

Errorcode: CC B8 01 28 21 05 10 07 6A D8

=====