

Old Mill Road Drainage Survey and Plan Markups

Brookhaven County Public Works - Field Survey Set - Control Date 2026-04-16

Sheet C-102: control point summary

Point	Northing	Easting	Elevation ft	Description	Status
BM-1	418223.22	1910442.10	217.862	Chiseled square on north headwall wing	Control
BM-2	418901.64	1910885.77	214.438	PK nail at power pole PP-17	Control
CHK-1	418505.44	1910648.30	216.042	Top of MH-2 rim	Survey tie

Sheet C-103: drainage structure survey

Structure	Station	Rim/gutter elevation ft	Pipe invert measured ft	Survey note
CB-1	10+02	216.82 gutter	P-1 out = 214.90	Matches network inventory.
MH-2	10+86	216.10 rim	P-1 in = 214.05; P-2 out = 214.05	Matches network inventory.
MH-3	11+82	215.58 rim	P-2 in = 213.12; P-3 out = 213.12	Matches upstream P-3 invert.
CB-3	12+40	214.92 gutter	P-3 in = 211.52; P-4 out = 211.88	Redline correction: P-3 downstream invert is 211.52 ft, not 211.92 ft.
OUT-1	13+14	213.80 headwall crown	P-4 out = 211.20; arch culvert invert = 210.85	Tailwater mark observed at 212.34 ft after April 9 storm.

Sheet C-104: drainage-area redline summary

Area label	Mapped area acres	Runoff character	Receiving node	Redline note
B1	2.10	Residential roofs and lawns	CB-1	Final polygon closed.
B2	not labeled on plan	Commercial frontage	CB-1	Area omitted from hydrology workbook; derive from signed total contributing area.
B3	2.75	School access and paved parking	MH-2	Final polygon closed.
B4	3.05	Roadway sag and sidewalk	CB-3	Controls local flooding complaint cluster.
B5	1.40	Open space and swale	OUT-1	Contributes near Willow Branch.
Signed total	11.40	All mapped drainage to OUT-1	OUT-1	Use this total to derive B2 if the workbook is blank.

Sheet C-105: plan-review comments

- Comment 04-16-A: The P-3 downstream invert shown in the 2024 GIS export is stale. Use the 2026 field measurement at CB-3.
- Comment 04-16-B: The HGL profile must show CB-1, MH-2, MH-3, CB-3, and OUT-1 against the current 0.30 ft clearance criterion.
- Comment 04-16-C: Willow Branch tailwater is uncertain because the April 9 observed mark may include debris blockage. Carry as open item unless verified.
- Comment 04-16-D: No DEM elevation may override this signed survey set without a written survey revision.