

RFI-221 Response

RFI	Response
RFI-221	Engineer response dated 2026-05-08 confirms valve relocation is required before ceiling close-in.
Coordination	Mechanical contractor must resequence work in Corridor B and coordinate with insulation subcontractor.