Vehicle diagnostic report

Shop Name: Russell Emptage

Address: 92230 Telephone: Email : Fax:

License #: bv64 zsu

Make: VW Model: Year: 2015

VIN: WV2ZZZ7HZFH034407 Mileage: 115790 (km)

Vehicle Software Version: V28.20

Diagnostic Application Version: V3.08.004

Test Time: 2017-09-21 09:28:20

Tester: russell emptage

Diagnostic path: Health Report

Diagnostic Result		
Fault	(5)	
09 Electronic Ctrl Electronics	(3)	Abnormal
	03224 Play protection active	
	00532 Supply voltage	Lower Limit Exceeded
	00446 Function limitation due to insufficient voltage	Lower Limit Exceeded
10 Parking Assist System 2	(2)	Abnormal
	U101100 Supply voltage - Voltage too low	passive/abiog enesis
	U140000 Function restriction-due to insufficient voltage	passive/abiog enesis
56 Radio	(1)	Abnormal
	00446 Function limitation due to insufficient voltage	Lower Limit Exceeded
61 Battery Control	(1)	Abnormal
	02256 Static current	Upper Limit Exceeded
77 Telephone	(1)	Abnormal
	U140000 Function restriction-due to insufficient voltage	passive/abiog enesis
Normal	(9)	
01 Engine Electronics		Normal
03 Brake Electronics		Normal
04 Steering Position		Normal
08 AC/Heating Electronics		Normal

15 Airbags17 Instrument Cluster18 Aux Heating19 Gateway Data Bus25 Immobilizer

Normal Normal Normal Normal