## Vehicle diagnostic report

Shop Name: chris longridge

Address: 89667 Telephone: Email: Fax:

License #: sn09nxv Make: LANDROVER Model: Defender

Year: 2010

VIN: SALLDVBS7AA783916

Mileage: 62592km

Vehicle Software Version: V33.04

Diagnostic Application Version: V3.07.010

Test Time: 2017-05-19 14:41:52

Diagnostic path: Automatically Search > Health Reports

**Diagnostic Result** 

Diagnostic Nesult		
Fault	(2)	
Instrument cluster control module.	(1)	Abnormal
	U0100-87 Lost communication with engine control module/powertrain control module 'A'	Historic
Powertrain control module	(3)	Abnormal
	P0404-72 Exhaust gas recirculation control - circuit range/performance	Intermittent
	P037D-29 Glow plug relay sense circuit	Permanent
	P0089-7a Fuel pressure regulator performance	Intermittent
Normal	(2)	
ABS control module		Normal
Vehicle immobilizer control module		Normal