## Vehicle diagnostic report

Shop Name: Russell Emptage

Address: 92230 Telephone: Email : Fax:

License #: oe13lka Make: Mercedes

Model: 246.200 - B 180 CDI

Year:

VIN: WDD2462002J185436

Mileage: 64818km

Vehicle Software Version: V48.70

Diagnostic Application Version: V3.08.004

Test Time: 2017-09-20 16:08:16

Tester: russell emptage

Diagnostic path: Automatically Search

Diagnostic Result Fault	(4)	
ECM - Engine Control Module(CDID3)for combustion engine 'OM651'(N3/9)	(1)	Abnormal
	U041500 Implausible data were received from control unit "ESP(R)"	STORED
SG-AWF - Control unit 'Distance warning function'(A90)	(1)	Abnormal
	C10C800 System "COLLISION PREVENTION ASSIST" has triggered a warning.	STORED
DCU_LF - Left front door(N69/1)	(1)	Abnormal
	B190915 The output for actuator motor "Additional door lock" has a malfunction. There is a short circuit to positive or an open circuit.	STORED
DCU_RF - Right front door(N69/2)	(1)	Abnormal
	B190915 The output for actuator motor "Additional door lock" has a malfunction. There is a short circuit to positive or an open circuit.	STORED
Normal	(14)	
FSCU_EC - Control unit 'Fuel pump'(N118)		Normal
TCM - Transmission Control Module(VGSFDKG(N15/1 3))		Normal
EFB - Electrical Parking Brake		Normal
ESP - Electronic stability program(N30/4)		Normal

EPS - Electronic Power Steering(N68)	Normal
EZS - Electronic ignition lock(N73)	Normal
SAM - Signal acquisition and actuation module(N10)	Normal
SRS - Supplemental restraint system(N2/10)	Normal
ATA - ATA[EDW]/tow- away protection/interior protection(N26/6)	Normal
IC - Instrument cluster(A1)	Normal
SCCM - Steering column module(N80)	Normal
PTS - PARKTRONIC(N62)	Normal
ZAN - Audio/COMAND display(A40/8)	Normal
AC - Air Conditioning(N22/7)	Normal