Vehicle diagnostic report

Shop Name: Russell Emptage

Address: 92230 Telephone: Email : Fax:

License #: ya14ahv Make: CITROEN

Model: C4 PICASSO (B78)

Year:

VIN: VF73A9HC8EJ746938 Mileage: 156875 (km)

Vehicle Software Version: V41.35

Diagnostic Application Version: V3.08.004

Test Time: 2017-09-06 09:04:48

Tester: russell emptage

Diagnostic path: Automatically Search>C4 PICASSO (B78)>Health Report

Diagnostic Result		
Fault	(10)	
Built-in system interface (BSI)	(12)	Abnormal
	B173e Fault in authenticating the mechanical/electronic key or the hands-free remote control present in the reader	Temporary fault
	B1718 Remote control not synchronised	Temporary fault
	B1626 Battery voltage fault	Temporary fault
	B1606 Battery charge status unit : configuration fault	Present
	B1715 lack of coherence between the vehicle locking status and the locking status of the front right door lock	Temporary fault
	B1716 lack of coherence between the vehicle locking status and the locking status of the front left door lock	Temporary fault
	B1418 Fault in the status of the seat belt fastening information for determining the presence of the driver	Temporary fault
	B173a Fault in the status of the driver's door for the determination of driver presence	Temporary fault
	B120a Collision risk alert function fault	Temporary fault
	B1209 Distance alert function or adapted cruise control function information fault	Temporary fault
	U1f32 Fault of absence of communication with the driver''s door control panel	Temporary fault
	U1f3c no communication with the diesel additive pump	Temporary fault
Engine System	(1)	Abnormal
	U1213 Intersystems CAN. One of the parameters present in a datastream sent by the ABS/ESP is invalid	Intermittent
Engine relay unit	(2)	Abnormal
	U1f04 Engine fuse box ECU internal fault.	Temporary fault

	B1138 Fault LH dipped beam.	Temporary fault
Switch module under the steering wheel(top of column)	(1)	Abnormal
	B1836 transponder aerial fault.	Permanent fault
Rain and brightness sensor	(4)	Abnormal
	U1f03 absence of communication fault with the built-in Systems Interface. U1807 Park information fault.	Temporary fault Temporary
	B1170 rain sensor fault.	fault Temporary fault
	U1f1a LIN fault.	Temporary fault
Parking aid	(9)	Abnormal
. arking ara	U1805 Wheel pulse counters information fault.	Temporary fault
	B1245 Rear right lateral parking assistance sensor fault.	Temporary fault
	B1250 Front left lateral parking assistance sensor fault.	Temporary fault
	B1251 Front right lateral parking assistance sensor fault.	Temporary fault
	B1223 Inner rear left parking assistance sensor fault.	Temporary fault
	B1227 Inner rear right parking assistance sensor fault.	Temporary fault
	B1224 Outer rear left parking assistance sensor fault.	Temporary fault
	B1228 Outer rear right parking assistance sensor fault.	Temporary fault
	B1244 Rear left lateral parking assistance sensor fault.	Temporary fault
Hands-free control unit	(1)	Abnormal
	B1724 Accesses unlocking sensor fault (front right-hand door).	Temporary fault
Electric power steering	(1)	Abnormal
	U131d Fault: no communication with parking assistance ECU. Not characterised	Permanent fault
Multiplexed diesel additive pump	(1)	Abnormal
	B2eb0 Additive reservoir empty fault.	Temporary fault
Driver's door module	(1)	Abnormal
	B1387 Driver's exterior mirror glass adjustment sensors fault.	Temporary fault
Normal	(19)	
Gearbox		Normal
Airbag		Normal
Anti-lock brake system Steering wheel with		Normal Normal
integral controls(VCI) Anti_theft alarm		Normal

Siren Air conditioning Vehicle distance assistance	Normal Normal Normal
Control panel RH reversible seat belt reel	Normal Normal
LH reversible seat belt reel	Normal
Battery charge status unit	Normal
Multiplexed control panel	Normal
Telematics unit SMEG_PLUS	Normal
Electric key reader Signalling fuse box Supply protection and management unit	Normal Normal Normal
Body control module Windscreen wiper	Normal Normal