Vehicle diagnostic report

Shop Name: Russell Emptage

Address: 92230 Telephone: Email : Fax:

License #: lt64hbk

Make: BMW Model: 520d Year: 2013.09

VIN: WBA5C32000D600843

Mileage:

Vehicle Software Version: V49.80

Diagnostic Application Version: V3.08.004

Test Time: 2017-09-20 11:15:21

Tester: russell emptage

Diagnostic path: Automatically Search > Health Report

Diagnostic Result Fault	(6)	
ECM (Engine Control Module - DME/DDE)	(2)	Abnormal
·	2B5400 Coolant pump, low temperature EGR, activation: Open circuit	Intermittent
	279800 Radiator shutter: Open limit position was detected too quickly.	Intermittent
ICM (Integrated Chassis Management)	(5)	Abnormal
	48010F DTC button, open circuit 482791 Pro-Active Driving Assistant Navigation data faulty 48010D Driving experience switch, sport button, line	Intermittent Intermittent Intermittent
	disconnection 48010E Driving experience switch, comfort button, line disconnection	Intermittent
SZL (Switch Center, Steering Column)	482714 Parking assistance button, line disconnection (1)	Intermittent Abnormal
,	C98420 SZL, FlexRay: communication fault	Intermittent
ZGM (Central Gateway Module)	(5)	Abnormal
	CD0420 ZGM, FlexRay controller signalling fault	Intermittent
	801C10 Request reset terminal 30F due to unauthorized waking	Intermittent
	801C11 Request deactivation terminal 30F due to unauthorized waking	Intermittent
	801C12 Send Power-Down command due to prevented sleeping	Intermittent
	801C13 Request reset terminal 30F due to prevented sleeping	Intermittent
IC (Instrument Cluster - INSTR)	(7)	Abnormal

	E11450 No message (terminals, 0x12F), receiver KOMBI, transmitter CAS/BDC	Intermittent
	E11454 No message (raw data, fuel tank level, 0x349), receiver KOMBI, transmitter JBE/BDC	Intermittent
	E1145C No message (display, engine speed, drive train, 0xF3), receiver instrument cluster, transmitter DME/DDE	Intermittent
	E11460 No message (data, display, transmission powertrain, 0x3FD), receiver KOMBI, transmitter EGS/DKG/EME	Intermittent
	E114CB No message (alive ZGM, 0xC0), receiver KOMBI, transmitter ZGM	Intermittent
	E11514 Message (longitudinal acceleration centre of gravity, ID 55.0.2) missing, receiver KOMBI, transmitter DSC/ICM	Intermittent
	E11515 Message (lateral acceleration centre of gravity, ID 55.0.2) missing, receiver KOMBI, transmitter DSC/ICM	Intermittent
CIC (Car Information Computer)	(1)	Abnormal
	B7F8C3 Connection between headunit and central information display (CID): No communication	Intermittent
Normal	(16)	
CAS (Car Access System) EKPS (Electronic Fuel		Normal Normal
pump) TCM (Transmission Control Module - EGS)		Normal
GWS (Gear Selector Switch)		Normal
ABS (Anti-lock Braking System - DSC)		Normal
EPB (Electrical Parking Brake - EMF)		Normal
EPS (Electronic Power Steering)		Normal
JBE/JBBF (Junction-box electronics)		Normal
SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM- SIM)		Normal
TEL (Telephone)		Normal
FZD (Function Center, Roof)		Normal
ECALL (Emergency Call)		Normal
PDC (Park Distance Control)		Normal
ZBE/CON (Controller)		Normal
FRM (Footwell Module)		Normal
AC (Air Conditioning - IHKA)		Normal