Vehicle diagnostic report

Shop Name: Russell Emptage

Address: 92230 Telephone: Email : Fax:

License #: rk63txc Make: Mercedes

Model: 176.012 - A 180 CDI DCT BlueEFFICIENCY Sedan

Year:

VIN: WDD1760122J186670

Mileage: 75815km

Vehicle Software Version: V48.70

Diagnostic Application Version: V3.08.004

Test Time: 2017-09-06 09:00:03

Tester: russell emptage

Diagnostic path: Automatically Search

| Diagnostic Result Fault | (4) | |
|--|--|----------|
| ECM - Engine Control Module(CDID3)for combustion engine 'OM651'(N3/9) | (1) | Abnormal |
| | P02023A The fuel injector (cylinder 3) has an electrical fault or an open circuit. The signal has too many pulses. | Stored |
| SG-AWF - Control unit 'Distance warning function'(A90) | (1) | Abnormal |
| | C10C800 System "COLLISION PREVENTION ASSIST" has triggered a warning. | STORED |
| DCU_LF - Left front door(N69/1) | (1) | Abnormal |
| | B190915 The output for actuator motor "Additional door lock" has a malfunction. There is a short circuit to positive or an open circuit. | STORED |
| DCU_RF - Right front door(N69/2) | (1) | Abnormal |
| | B190915 The output for actuator motor "Additional door lock" has a malfunction. There is a short circuit to positive or an open circuit. | STORED |
| Normal | (14) | |
| FSCU_EC - Control unit 'Fuel pump'(N118) | | Normal |
| EFB - Electrical Parking Brake | | Normal |
| ESP - Electronic stability program(N30/4) | | Normal |
| EPS - Electronic Power Steering(N68) | | Normal |
| EZS - Electronic ignition lock(N73) | | Normal |

| N | Normal |
|--|--------|
| , the state of the | Normal |
| N | Normal |
| | |