## Vehicle diagnostic report

Shop Name: Russell Emptage

Address: 92230 Telephone: Email : Fax:

License #: wg11nzz Make: SUBARU

Model: Year: VIN: null Mileage:

Vehicle Software Version: V23.20

Diagnostic Application Version: 3.08.001

Test Time: 2017-06-29 12:02:39

Tester: russell emptage

Diagnostic path: 16 PIN SOCKET > Health Report



Diagnostic Result

Fault	(3)	
ABS (Anti-lock Braking System)	(2)	Abnormal
	C0071 Steering Angle Sensor malfunction C0047 Improper CAN Communication	
IUM (Integ. unit mode)	(5)	Abnormal
	B0101 BATT p/supply malfunction cont. B0102 BATT p/supply malfunction backup B0103 Ignition power failure B0104 ACC power failure B0221 CAN-HS ECM no-receive data	
CS (CAN System)	(1)	Abnormal
	U1221 CAN-HS ECU no-receive data(Fault Location: Comm.Line Failure(ECM to Integ. Unit) or ECM Failur	
Normal	(3)	
ECM (Engine Control Module)		Normal
TCM (Transmission Control Module)		Normal
SRS (Supplemental Inflatable Restraint System)		Normal