Vehicle diagnostic report

Shop Name: Russell Emptage

Address: 92230 Telephone: Email : Fax:

License #: vo60rgy Make: MAZDA

Model: MAZDA6 (GH, After Facelift) / ATENZA

Year:

VIN: JMZGHA9A601432960

Mileage:

Vehicle Software Version: V40.96

Diagnostic Application Version: V3.08.004

Test Time: 2017-09-20 16:38:06

Tester: russell emptage

Diagnostic path: Automatically Search > 16PIN DIAGNOSTIC SOCKET > Health Reports

Diagnostic Result

Diagnostic Result		
Fault	(9)	
ABS (Anti-Lock Brake System)	(1)	Abnormal
	C0051 Steering Wheel Position Sensor	Continuous Memory DTC -
ACU (Audio Control Unit)	(2)	Abnormal
	U3003 Battery Voltage	Continuous Memory DTC -
	B1188 CD Read Test Failure	Continuous Memory DTC -
AFS (Adaptive Front Steering)	(1)	Abnormal
	U3003 Battery Voltage	Continuous Memory DTC -
BCM/GEM (Body Control Module/Generic Electronic Module)	(1)	Abnormal
	U3003 Battery Voltage	Continuous Memory DTC -
IC (Instrument Cluster)	(1)	Abnormal
	U3003 Battery Voltage	Continuous Memory DTC -
RKE (Remote Keyless Entry)	(4)	Abnormal
	B10D7 PATS(Passive Anti Theft System) Key	Continuous Memory DTC -
	U3003 Battery Voltage	Continuous Memory DTC -
	P1794 Battery Voltage Circuit	Continuous Memory DTC -
	P0560 System Voltage	Continuous Memory DTC -

PCM (Powertrain Control Module)	(2)	Abnormal
	P0562 System Voltage Low	Continuous Memory DTC -
	P1260 Theft Detected, Vehicle Immobilized	Continuous Memory DTC -
RCM (Restraint Control Module)	(1)	Abnormal
	U3003 Battery Voltage	Continuous Memory DTC -
RVM (Rear Vehicle Monitoring)	(1)	Abnormal
	U3003 Battery Voltage	Continuous Memory DTC -
Normal	(2)	Ť
EATC (Electronic Automatic Temperature Control)		Normal
EPS (Electronic Power Steering)		Normal