MIPS instructions codes

a. Codes of the Opcode fields - IR(31 downto 26)

```
=[101011]=43
SW
lw
       =[100011]=35
lui
       =[001111]=15
       =[001101]=13
ori
       =[001000]=8
addi
beq
       =[000100]=4
bne
       =[000101]=5
j
       =[000010]=2
       =[000011]=3
jal
R-type =[000000]=0
```

b. Function field codes for RType instructions - IR(5 downto 0)

```
add =[100000]=32

sub =[100010]=34

and =[100100]=36

or =[100101]=37

xor =[100110]=38

slt =[101010]=42

jr =[001000]=8
```

Rs, Rt and Rd fields have a 5 bit binary number of the register (0-31)