

MATERIAL SAFETY DATA SHEET

SILICONE ADHESIVE REMOVER

1. CHEMICAL PRODUCT AND COMPANY IDENTIFICATION

MANUFACTURER:

WESMAR PRODUCTS, INC.
1440 N.W. 45th STREET
SEATTLE, WA 98107
(206) 782-8186

INFORMATION PHONE:

EMERGENCY PHONE:

CHEMTREC 800-242-9300 (US) Day or night
International Call Collect CHEMTREC 202-483-7616

Print Date: 9/5/2001

SECTION I - PRODUCT IDENTIFICATION

PRODUCT NAME: SILICONE ADHESIVE REMOVER

PRODUCT NUMBER: WM 4321 - WM 4325

UPC NUMBER:

PREPARED BY Patricia Rodabaugh

DATE PREPARED: 4/13/2001

LAST REVISION: 4/13/2001

DOT CLASS: Flammable liquid

UN NUMBER: UN 1268

PACKING: II

GUIDE NUMBER: 128

SHIPPING NAME: Petroleum distillates, n.o.s. (toluene, naphtha solvent)

SYNONYMS:

SECTION II - HAZARDOUS INGREDIENTS

Chemical Name	CAS #	Weight %	OSHA PEL	ACGIH TLV
Solvent naphtha, mineral spirits	64742-88-7	50-58	100 ppm*	100 ppm*
Xylenes	1330-20-7	1-2	100 ppm	100 ppm
Trimethylbenzene, 1,2,4,-	95-63-6	1-4	25 ppm	25 ppm
Toluene	108-88-3	42-48	200 ppm	50 ppm (skin)

SECTION III - PHYSICAL CHARACTERISTICS

BOILING POINT: 337

VAPOR PRESSURE: 1 mm @ 56 deg F

EVAPORATION: Slower than ether

POUNDS PER GALLON: 6.77

SPECIFIC GRAVITY: 0.88

MELTING POINT: NDA

VAPOR DENSITY: Heavier than air

PH: essential neutr

SOLUABILITY IN WATER: Solubility negligible in water

APPEARANCE AND ODOR: Colorless, clear liquid. Mild odor.

SECTION IV - FIRE/EXPLOSION

FLASH POINT: 75 F

FLASH POINT METHOD USED: Tag Closed Cup

LEL: 0.009

UEL: 0.07

EXTINGUISHING MEDIA:

Use water fog, "alcohol" foam, dry chemical, or CO2.

SPECIAL FIRE FIGHTING PROCEDURES:

WARNING. Flammable Liquid. Clear fire area of unprotected personnel. Do not enter confined fire space without full bunker gear, including a positive pressure NIOSH approved SCBA. Cool fire exposed containers with water.

UNUSUAL FIRE AND EXPLOSION HAZARDS:

When heated above the flash point this material emits flammable vapors which, when mixed with air, can burn or be explosive. Fine mist or spray may be flammable at temperatures below the flash point.

SECTION V - REACTIVITY DATA**STABLE:**

Stable

INCOMPATIBILITY:

Strong oxidizers.

HAZARDOUS DECOMPOSITION OR BY PRODUCTS:

Carbon monoxide and unidentified organic compounds may be formed during combustion.

HAZARDOUS POLYMERIZATION:

Will Not Occur

SECTION VI - HEALTH HAZARD DATA**ACUTE HEALTH EFFECT**

- EYE CONTACT:** Liquid is moderately irritating to the eyes. High vapor concentrations may also be irritating.
- INHALATION:** Vapors may be irritating to the nose, throat, and respiratory tract. High vapor concentrations may cause central nervous system (CNS) depression.
- INGESTION:** Liquid is moderately toxic and may be harmful if swallowed; may produce CNS depression. Ingestion of product may result in vomiting; aspiration (breathing) of vomitus into the lungs must be avoided as even small quantities may result in aspir. pneumonitis.
- SKIN CONTACT:** Liquid is moderately irritating to the skin. Prolonged or repeated contact can result in defatting and drying of the skin which may result in skin irritation and dermatitis (rash).

SIGNS AND SYMPTOMS OF EXPOSURE:

Early to moderate CNS depression may be evidenced by giddiness, headache, dizziness, and nausea; in extreme cases, unconsciousness and death may occur. Aspiration pneumonitis may be evidenced by coughing, labored breathing and cyanosis.

AGGRAVATED MEDICAL CONDITIONS:

May cause skin and liver disease, may attack respiratory tract. Laboratory studies have shown that petroleum distillates may cause kidney, liver, or lung damage. reports have associated repeated and prolonged overexposure to solvents with permanent brain and nervous system damage.

SUPPLEMENTAL HEALTH INFORMATION:

Male rats exposed for 90 days by inhalation to vapors of similar solvents showed evidence of kidney damage. The relevance of this effect to humans is unknown. In one of the studies a low grade anemia was also observed.

EMERGENCY FIRST AID PROCEDURES

- EYE CONTACT:** Immediately flush eyes with plenty of water for at least 15 minutes while holding eyelids open. If irritation persists, get medical attention.
- INHALATION:** Remove victim to fresh air. If not breathing, give artificial respiration. If breathing is difficult, oxygen should be administered by qualified personnel. Get medical attention.
- INGESTION:** DO NOT INDUCE VOMITING. If vomiting occurs spontaneously, keep head below hips to prevent aspiration of liquid into the lungs. Get medical attention.
- SKIN CONTACT:** Remove contaminated clothing/shoes. Flush skin with water. Follow by washing with soap and water. If irritation occurs, get medical attention. Do not reuse clothing until cleaned.

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS SPILLED OR RELEASED:

WARNING. Flammable. Ventilate area of leak or spill. Remove all sources of ignition. Clean-up personnel require protective clothing and respiratory protection from vapors. Only specially trained or qualified personnel should handle the emergency.

WASTE DISPOSAL METHOD:

The preferred options for disposal are to send to licensed reclaimers, or to permitted incinerators. Any disposal practice must be in compliance with federal, state, and local regulations. Do not dump into sewers, ground, or any body of water.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE:

Keep away from heat, sparks, and flame. Surfaces that are hot may ignite even liquid product in the absence of sparks or flame. Extinguish pilot lights, cigarettes and turn off other sources of ignition prior to use and until all vapors are gone.

OTHER PRECAUTIONS:

KEEP OUT OF REACH OF CHILDREN! Empty containers retain product residue and can be dangerous. Do not pressurize, cut weld, braze, solder, drill, grind, or expose such containers to heat, flame, sparks static electricity, or other sources of ignition.

SECTION VIII - CONTROL MEASURES

RESPIRATORY PROTECTION:

If exposure may or does exceed occupational exposure limits (Sec. 2) use a NIOSH approved respirator to prevent overexposure. In accord with 29 CFR 1910.134 use either an atmosphere-supplying respir. or an air-purifying respir. for organic vapors.

VENTILATION:

Provide exhaust ventilation sufficient to keep the airborne concentration of this product below its exposure limits. Exhaust air may need to be cleaned by scrubbers or filters to reduce environmental contamination.

PROTECTIVE GLOVES:

Test data indicate the best protection is provided by neoprene, nitrile, and natural rubber gloves.

EYE PROTECTION:

Use chemical safety goggles and/or full face shield where splashing is possible. Contact lenses should not be worn when working with this material. Maintain eye wash fountain and quick-drench facilities in work areas.

OTHER PROTECTIVE CLOTHING OR EQUIPMENT:

Where splashing is possible, full chemically resistant protective clothing (e.g., acid suit) and boots are required.

WORK / HYGENIC PRACTICES:

Use good personal hygiene when handling this product. Wash hands after use, before eating, drinking, smoking, or using the toilet.

The information contained herein is based on the data available to us and is believed to be accurate. However, expressed or implied regarding the accuracy of these data or the results to be obtained from the use thereof. from the use of the product described herein.

makes no warranty,
assumes no responsibility for injuries