

ARDUINO TEMPERATURE DISPLAY USING DHT22 SENSOR AND 16x2 LCD

Components Required

Arduino Uno
DHT22 Temperature & Humidity Sensor
16x2 LCD with I2C Module
Breadboard
Jumper Wires
USB Cable

Working

The Arduino Uno reads temperature and humidity from the DHT22 sensor. The measured temperature and humidity values are displayed on a 16x2 LCD using the I2C interface. If the sensor fails to respond, the LCD displays 'Sensor Error'. This project is useful for weather monitoring, room temperature monitoring, laboratories, smart homes, and IoT applications.

Connections

Component	Arduino Uno Pin
DHT22 VCC	5V
DHT22 DATA	D2
DHT22 GND	GND
LCD VCC	5V
LCD GND	GND
LCD SDA	A4
LCD SCL	A5

Output

LCD Line 1: Temp: 24°C

LCD Line 2: Hum : 40%

PROJECT LINK

<https://wokwi.com/projects/468965135566441473>