




7.1 Tracking (Integral-Only Control)




7.2 Proportional-Only Control (No Steady-State Elimination)



7.3 Integral Windup Demonstration and Recovery



7.4 Instability from Excessive Gains



7.5 External Disturbance Rejection

