




## 7.1 Tracking (Integral-Only Control)




## 7.2 Proportional-Only Control (No Steady-State Elimination)



### 7.3 Integral Windup Demonstration and Recovery



## 7.4 Instability from Excessive Gains



## 7.5 External Disturbance Rejection

