Notification Number: 1992/356/UK

# TR 2140 - MOTORWAY SIGNALS MARK 2 REQUIREMENTS FOR CANTILEVER STRUCTURES

Date received : 04/01/1993 End of Standstill : 13/04/1993

# Message

MINISTERE DE L'INDUSTRIE ET DE LA RECHERCHE ATT. M. MORTUREUX

SECRET. GENERAL COMITE INTERMINISTERE

INSTITUT BELGE DE NORMALISATION, ATT. M. CROON

INSPECTION DU TRAVAIL ET DES MINES VIA MINISTERE DES AFFAIRES ETRANGERES ATT. M. A. SCHUSTER

MINISTERE DE L'INDUSTRIE ATT. M. CAVANNA

DEPT. OF TRADE AND INDUSTRY, QUALITY AND EDUCATION DIVISION, ATT. MR. E. ALLEN

GOVERNMENT SERVICE OF INDUSTRY AND COMMERCE, NSAI ATT. MR. J. NULTY

MINISTERIE VAN ECONOMISCHE ZAKEN, (DG BEB), ATT. MR. B. SIEBRING

INDUSTRI- OG HANDELSSTYRELSEN ATT. MR. KELD DYBKJAER

AGENCE RECHERCHE SCIENTIFIQUE TECHN ATT. MME. MOUSTAKA-ZERVAKOU

HELLINIKOS ORG. TYPOPISEOS ATT. MR. MELAGRAKIS

MIN WIRTSCHAFT ATT. DR. WINKEL

MIN PARA RELACIONES CON LA COMUNIDA

ATT MR. D. ALFREDO RAMBLA JOVANI

MIN INDUSTRIA

ATT MR. ADALBERTO PEREA MARTIN, ESPAGNE

MINISTERIO DA SAUDE

INSTITUTO DA QUALIDADE ALIMENTAR

DIRECCIO GERAL QUALIDAD ATT MR. CANDIDO DOS SANTOS, PORTUGAL

DGS INTERNATIONAL BELGIUM

REP PERMANENTE ROYAUME UNI

REP PERMANENTE IRLANDE

REP PERMANENTE GRECE

ICC: PLEASE FORWARD THIS MESSAGE TO ICC MAILBOX EFTBT

TELEX 001

COMMUNICATION FROM THE COMMISSION - SG (92) D/52210 DIRECTIVES 83/189/EEC AND 88/182/EEC

NOTIFIKATION - NOTIFIZIERUNG - NOTIFICATION - NOTIFICACION NOTIFICATION - NOTIFICA - KENNISGEVING - NOTIFICACAO 92/0356/UK

FRISTERNE INDLEDES IKKE -KEIN FRISTBEGINN - DOES NOT OPEN THE DELAYS - NO ABRE EL PLAZO - N'OUVRE PAS DE DELAIS - NON FA DECORRERE LA MORA - GEEN TERMIJNBEGIN - NAO INICIA O PRAZO

- 3B2: 9300022.EN

## 1. Structured Information Line

TLX 001 IND- 92 0356 UK- EN ----- 930104 --- ---

#### 2. Member State

UNITED KINGDOM

#### 3. Department Responsible

DEPARTMENT OF TRADE AND INDUSTRY: STANDARDS, QUALITY AND POLICY UNIT

## 3. Originating Department

DEPARTMENT OF TRANSPORT

## 4. Notification Number

92/0356/UK



#### 5. Title

TR 2140 - MOTORWAY SIGNALS MARK 2
REQUIREMENTS FOR CANTILEVER STRUCTURES

#### 6. Products Concerned

CANTILEVER STRUCTURES FOR MOTORWAY SIGNALS

## 7. Notification Under Another Act

-

#### 8. Main Content

THIS REQUIREMENT IS PART OF A SET OF REQUIREMENTS DEFINING THE MOTORWAY SIGNAL MARK 2 EQUIPMENT.
THE CANTILEVER STRUCTURE IS DESIGNED TO SUPPORT A MOTORWAY SIGNAL AND IS INSTALLED IN THE MOTORWAY VERGE

#### 9. Brief Statement of Grounds

THE DEPARTMENT OF TRANSPORT REQUIRES THAT MOTORWAY SIGNALS MARK 2 ARE SUPPLIED AND INSTALLED TO DEFINED STANDARDS THIS SPECIFICATION DEFINES THE REQUIREMENTS FOR CANTILEVER STRUCTURES

#### 10. Reference Documents - Basic Texts

DRAFT DOCUMENT:

TR 2140: MOTORWAY SIGNALS MARK 2

TR 2141 - TR 2142 - TRH 1642 - TRH 1677 - TRH 1678 - TRG 1069

**BASIC TEXTS:** 

FORM BE/P2 - FORM BE/P3 - FORM BE/P4 - FORM BE/P5 -

BS 5400 PART 4 - BS 7430 - BS 8118 PART 1

## 11. Invocation of the Emergency Procedure

NO

# 12. Grounds for the Emergency

-

D. WILLIAMSON COMEUR NNNN