Notification Number: 2010/108/UK

Interim Advice Note 93/10 – Driver Location Signs: Interim Requirements.

Date received : 18/02/2010

End of Standstill : 19/05/2010 (19/08/2010)

Issue of detailed opinion by : Commission

Message

Message 001

Communication from the Commission - SG(2010) D/5441

Directive 98/34/EC

Notificación - Oznámení - Notifikation - Notifizierung - Teavitamine - Γνωστοποίηση - Notification - Notifica - Pieteikums - Pranešimas - Bejelentés - Notifika - Kennisgeving - Zawiadomienie - Notificacão - Hlásenie-Obvestilo - Ilmoitus - Anmälan - Нотификация : 2010/0108/UK - Notificare.

No abre el plazo - Nezahajuje odklady - Fristerne indledes ikke - Kein Fristbeginn - Viivituste perioodi ei avata - Καμμία έναρξη προθεσμίας - Does not open the delays - N'ouvre pas de délais - Non fa decorrere la mora - Neietekmē atlikšanu - Atidėjimai nepradedami - Nem nyitja meg a késéseket - Ma' jiftaħx il-perijodi ta' dawmien - Geen termijnbegin - Nie otwiera opóźnień - Nao inicia o prazo - Neotvorí oneskorenia - Ne uvaja zamud - Мääräaika ei ala tästä - Inleder ingen frist - Не се предвижда период на прекъсване - Nu deschide perioadele de stagnare - Nu deschide perioadele de stagnare.

(MSG: 201000441.EN)

1. Structured Information Line

MSG 001 IND 2010 0108 UK EN 18-02-2010 UK NOTIF

2. Member State

UK

3. Department Responsible

Department for Business, Innovation and Skills Innovation & Enterprise Group

1 Victoria Street, London, SW1H 0ET.

Email: 9834@bis.gsi.gov.uk.

3. Originating Department

Highways Agency

4. Notification Number

2010/0108/UK - T40T

5. Title

Interim Advice Note 93/10 – Driver Location Signs: Interim Requirements.

6. Products Concerned

Driver location signs to be installed on the English Strategic Road Network.

7. Notification Under Another Act

_

8. Main Content

This document gives the Highways Agency's requirements for product compliance and location of driver location signs on the English Strategic Road Network.

9. Brief Statement of Grounds

- i. To align the Highways Agency's requirements and guidance with the requirements of BS EN 12899-1:2007 and the Construction Products Directive (89/106/EEC) with respect to driver location signs.
- ii. To improve the safety of road users by providing an additional aid to facilitate them to more easily identify their location on the network in the event of a breakdown or incident.

10. Reference Documents - Basic Texts

References of the Basic Texts: BS EN 12899-1: 2007. Fixed, vertical road traffic signs Part 1. Fixed signs.

TD 46/05 Network Traffic Control and Communications. Standards of Provision. Motorway Signalling - Chapter 4: Drawings

TD 22/06 Road Geometry. Junctions. Layout of Grade Separated Junctions - Figure 1/1: Definition of Main Terms

TA 77/97 Network Traffic Control and Communications. Infrastructure Design. Motorways - Annex A Chapter A13: Geographic Addressing.

HD 19/03 Assessment and Preparation of Road Schemes. Preparation and Implementation. Road Safety Audit. Basic Texts have been forwarded within the framework of a previous notification: 2001/0373/UK

11. Invocation of the Emergency Procedure

No

12. Grounds for the Emergency

-



13. Confidentiality

No

14. Fiscal measures

No

15. Impact assessment

Impact assessment not available.

16. TBT and SPS aspects

TBT aspect

No - The draft is in conformity with an international standard

SPS aspect

No - The draft is not a sanitary or phytosanitary measure

Catherine Day General Secretary European Commission

Contact point Directive 98/34

Fax: (32-2) 296 76 60

email: dir83-189-central@ec.europa.eu