
INNER REAR VIEW MIRROR ASSY REPLACEMENT

7011V 01

HINT:

- The installation procedures are the new alprocedures in reverse order.
- Use[the[same[procedures[for[the[RH]side]and[LH]side].
- The procedures listed below are for the LH side.
- $\bullet \ \ \, \triangle \ \ \, A[bolt] without] \ \ \, a[continue] \ \ \,$




1. REMOVE MAP LAMP ASSY

- (a) Open the upper console.
- (b) Using a screwdriver, pry out the lens cover.

HINT:

Tape the screwdriver tip before use.




(c) Using a screwdriver, pry out the 2 caps.

HINT:

Tape the screwdriver tip before use.

- (d) Remove the 4 screws.
- (e) Remove the map lamp and disconnect the connector.



2. REMOVE INNER REAR VIEW MIRROR ASSY

- (a) Remove the 2 screws and mirror.
- (b) Disengage the connector from the body.