Z

1 LS 430 (RHD) ELECTRICAL WIRING DIAGRAM Multiplex Communication System (Gateway ECU) Power Source 2 R-W I17 IGNITION SW J13 A, J14 B J13 A JUNCTION CONNECTOR JUNCTION CONNECTOR 4 13 (DE) G 1 GATEWAY ECU ACC CG MPL2 GTX+ GND MPI1 MPI2 MPD1 MPD2 MPL1 7 (DG) 1 (4A) BATTERY Left side of shift lever Right side of