## ENGINE IMMOBILISER SYSTEM HOW TO PROCEED WITH TROUBLESHOOTING

DI1AJ-26

Troubleshoot in accordance with the procedure on the following pages. HINT:

This ECU is connected to the multiplex communication system. Therefore, be sure to check that there is no troubles in the multiplex communication system before performing the troubleshooting.

