COMBINATION SWITCH CONTROL SYSTEM HOW TO PROCEED WITH TROUBLESHOOTING

DISI P_01

HINT:

The ECU of this system is connected to the maltiplex communication system. Therefore, before starting troubleshooting, make sure to check that there is no trouble in the maltiplex communication system.

