## **PROBLEM SYMPTOMS TABLE**

05l30-01

Symptom	Suspected Area	See Page
Key reminder buzzer does not sound	1. Front door courtesy lamp switch circuit (driver side)	05-2987
	2. Combination meter assy	05-2151
	3. Power source circuit	05-2985