2902K-02

PROBLEM[\$YMPTOMS[TABLE

Use[the[table[below[to[help[you[find[the[cause]]]]]] the problem. The flumbers indicate the priority of the likely cause of the problem. Check each part in order. If the cessary, replace these parts.

Symptom	Suspected Area	See page
Noise in rear differential	1. Oil level (Low or wrong grade)	29–7
	2. Ring gear or drive pinion (Worn or chipped.)	29-7
	3. Backlash adjustment (Defective)	29-7
	4. Preload adjustment (Defective)	29-7
	5. Tooth contact between ring gear and drive pinion	
	(Defective)	29-7
	6. Bearing (Worn)	29–7
Oil leak from rear differential	Oil level (Too high or wrong grade)	29–5
	2. Oil seal (Worn or damaged)	29-6
	3. Gasket (Damaged)	29-7
	4. Seal packing (Damaged)	29–7