DI7PB-04

18. GPS mark does not appear.

INSPECTION PROCEDURE

1 Check mark display. (At place with fine view, is GPS mark displayed or not?)

Yes

Normal.

No

2 Check connection of navigation antenna. (Bite or sharp bend)

NG

Connect navigation antenna properly.

OK

3 Check optional components. (Does GPS mark appear normally if optionals such as theft deterrent system is removed?)

Yes

Remove them or change position of components.

HINT:

Some optionals receive radio signals. This may affect GPS reception.

No

4 Is there anything such as a film stuck to window or any metal object on instrument panel?

Yes⊡

Reception may be affected by a screen such as a film.

No

5 | Service check mode. [Is] 58-40, [41" is output in unit check mode of navigation ECU?) [See page DI-1600).

Yes

Troubleshoot for each diagnosis.

No

Replace navigation antenna.

HINT:

If the trouble still occurs, replace the navigation ECU.