PHARTOTION THOURSON THE OWER PETER WAS TO TEM
HOW[TO[PROCEED[WITH[TROUBLESHOOTING]
1 VEHICLE BROUGHT TO WORKSHOP
2 CUSTOMER[PROBLEM[ANALYSIS[SEE[PAGE[05-663)
3 PROBLEM SYMPTOM CONFIRMATION
SYMPTOM[DOES[NOT[DCCUR[(GO[TO[STEP]4)
SYMPTOM[DCCUR[[GO[]TO[STEP[5])
4 SYMPTOM SIMULATION (SEE PAGE 01-34)
5 PROBLEM SYMPTOMS TABLE (SEE PAGE 05-666)
6 CIRCUIT INSPECTION (SEE PAGE 05-667 TO 05-676)
7 IDENTIFICATION OF PROBLEM
8 REPAIR
9 CONFIRMATION TEST
END