STEERING SYSTEM PRECAUTION

5009II 0

1. HANDLING [PRECAUTIONS [FOR [STEERING [SYSTEM]

- (a) Care must be aken when peplacing parts. Incorrect peplacement could affect the performance of the steering system and result in a driving hazard.
- 2. | HANDLING[PRECAUTIONS[FOR[\$RS[AIRBAG[\$YSTEM
- (a) The LS430 [sequipped with RS[Supplemental Restraint System) such as the driver air bag and front passenger air bag, etc. Failure to carry out service operations in the correct sequence could cause the SRS to mexpectedly deploy during servicing, possibly leading to a serious accident. Before servicing (including moval or installation of parts, inspection or replacement), be sure to read the precaution ary notice for the supplemental restraint system (see page 60–1).