260HQ-01

## **REPAIR**

## HINT:

This is the repair procedure for vehicle pull.

