SLIDING ROOF SYSTEM HOW TO PROCEED WITH TROUBLESHOOTING

DITEK OF

HINT:

The ECU of this system is connected to the multiplex communication system. Therefore, before starting troubleshooting, be sure to check that there is no trouble in the multiplex communication system.

