INSTRUMENT PANEL SAFETY PAD SUB-ASSY PRECAUTION

710L0-01

1. HANDLING PRECAUTIONS FOR STEERING SYSTEM

- (a) Care must be taken when replacing parts. Incorrect replacement could affect the performance of the steering system and result in a driving hazard.
- 2. HANDLING PRECAUTIONS FOR SRS AIRBAG SYSTEM
- (a) The LS430 is equipped with SRS (Supplemental Restraint System) such as the driver airbag and front passenger airbag, etc. Failure to carry out service operations in the correct sequence could cause the SRS to unexpectedly deploy during servicing, possibly leading to a serious accident. Before servicing (including removal or installation of parts, inspection or replacement), be sure to read the precaution-ary[hotice]for[he[supplemental]restraint[system]see[page[60-1)]