
05HDB-01


DISPLAY CHECK MODE COLOR BAR CHECK)

HINT:


- This mode checks the color display on the multi-display.
- Illustrations may differ from the actual yehicle depending on the device settings and options. Therefore, some detailed areas may not be shown exactly the same as on the actual yehicle.
- 1. Enter diagnostic mode see page 5-1780).



2. Select "Display Check" from the "Diagnosis MENU" screen.



3. Select "Color Bar Check" from the "Display Check" screen.



4. Select a color bar from the "Color Bar Check Mode" screen.

HINT:

- The entire screen turns to the color or stripe selected.
- Touching the display will return to the "Color Bar Check" screen.