HOW[TO[PROCEED[WITH[TROUBLESHOOTING]	
1 V	VEHICLE[BROUGHT[TO[WORKSHOP
2 0	CUSTOMER[PROBLEM[ANALYSIS[[SEE[PAGE[05-2149]
3□ P	PROBLEM SYMPTOM CONFIRMATION (SEE PAGE 05-2151)
4□ 0	CHECK[MULTIPLEX[COMMUNICATION[\$YSTEM[(SEE[PAGE[05-3140)
	MULTIPLEX[] DTC[] OUTPUTS[] (PROCEED[] TO "BODY[] MULTIPLEX[] COMMUNICATION[] SYSTEM") NO[MULTIPLEX[DTC[GO[TO[STEP[5])] CHECK[CAN[COMMUNICATION[SYSTEM[[SEE[PAGE[05-3306])]
(a)∏ Chec	ck[for[DTC[outputs.
\	CANIDTCIDUTPUTS[IPROCEED[TO]]*CANIDOM-MUNICATION[\$YSTEM")
	NO[CAN[DTC[GO[TO[\$TEP[6])
6□ C	CIRCUIT[INSPECTION[[SEE[PAGE[05-2168-[05-2201]
7 F	REPAIR OR REPLACE
8 0	CONFIRMATION TEST
END	