## 5. Diagnosis

The following DTC has been changed, along with the changes in the brake actuator and the adoption of CAN communication.

## **▶** DTC Chart (blinking ABS warning light) **◄**

	DTC No.		Detection House
	2-digit	5-digit	Detection Item
Added DTC	91	C1361	Short circuit in ABS motor cut off relay circuit
	94	U0073	CAN (Controller Area Network) communication circuit malfunction
	95	U0124	Deceleration sensor communication circuit malfunction
	97	C1381	Yaw late & deceleration sensor power source voltage (IG) is abnormal
Discontinued DTC	26	C1226	Open or short circuit in brake actuator solenoid circuit (SRM circuit)
	27	C1227	Open or short circuit in brake actuator solenoid circuit (SRC circuit)

## **▶** DTC Chart (blinking VSC warning light) **◄**

	DTC No.		Datastian Hama
	2-digit	5-digit	Detection Item
Added DTC	43	C1223	Malfunction in ABS relation
	62	U0123	Yaw rate sensor communication circuit malfunction
	63	U0126	Steering angle sensor communication circuit malfunction
	65	U0100	Engine ECU communication circuit malfunction
Discontinued DTC	33	C1233	Open or short circuit in yaw rate sensor circuit
	35	C1335	Open circuit in steering angle sensor
	44	C1224	Open or short circuit in NEO signal circuit
	52	C1202	Brake fluid level low/ Open circuit in brake fluid level warning switch
			circuit
	57	C1303	Malfunction in multiplex communication circuit