DI8SA-01

DTC	B2794	Unmatched Encryption Code
-----	-------	---------------------------

CIRCUIT DESCRIPTION

This DTC is detected when the code, which is decoded in the Transponder Key (Steering Lock) ECU, and the code received from the key are not matched during the key code varification. Replace the key when this DTC is detected.

DTC No.	DTC Detecting Condition	Trouble Area
B2794	Transponder chip malfunction	• Key (Smart Key)

INSPECTION PROCEDURE

Replace key (smart key)	
-------------------------	--