
DI7PA-04

17. [Vehicle position is deviated from correct point badly.



No

DIAGNOSTICS - LEXUS NAVIGATION SYSTEM 5∏ Navigation check mode. (Vehicle signal check mode: SPD) (See page DI-1600) Replace or repair speed sensor wire harness NG (See page N-35). OK Recurrence test (Confirm phenomenon) (Correct current position and drive ve-6 hicle for a while with GPS mark displayed.) OK Normal. NG Replace navigation ECU (See page N-35). 7 Check connection of navigation antenna. (Bite or sharp bend) NG Connect navigation antenna properly. OK 8 Check optional components. (Does GPS mark appear if optionals such as theft deterrent system is removed?)

> Remove them or change position of compo-Yes

HINT:

nents.

Some optionals receive radio signals. This may affect GPS reception.

No

9 | Is[there@anything@such@as@film@stuck@to@window@or@any@metal@bject@on@nstrument@panel?

Yes

Reception may be affected by a screen such as a film.

No

10 | Service check mode. (Is 358-40, 41" is output in unit check mode of navigation ECU?) (See page DI-1500).

Yes□

Troubleshoot for each diagnosis.

No

Replace navigation antenna See page IN-35).

HINT:

If the trouble still occurs, replace the navigation ECU.