## 12.10.2024/Cumartesi Bilimsel Endustriyel ve Teknolojik Araştırma ve Uygulama Merkezi 11:45 12:30 12:50 13:20 13:40 15:50 17:30 17:50 18:20 Sensor Matrix 14:10 14:30 15:00 15:20 16:10 16:40 17:00 18:40 Matrix 1 Heating Z100 A0 Air ✓ Z95 A5 Air Z90 A10 ✓ Air Z80\_A20 **√** Air ✓ Z70\_A30 **√** Air Z50\_A50 ✓ Air Z0\_A100 Air **√** Finish 11:45 12:30 12:50 13:20 13:40 14:10 14:30 15:00 15:20 15:50 16:10 16:40 17:00 17:30 17:50 18:20 18:40 Matrix 2 Heating ✓ Z95 A5 Z90\_A10 ✓ Air ✓ Z80\_A20 Air Z70\_A30 ✓ Air Z50\_A50 **√** Air ZO A100 Air Z100 A0 Air Finish ✓