
NGSPICE

- .temp 27
- .ic v(v_out)=0
 .option method=gear
- .control
 tran 0.005u 15u uic
 plot v_ena v_out

let vout_limit=0.8*0.99
meas tran tcross WHEN v(v_out)=vout_limit
let vena_limit=0.5*1.5
meas tran tstart WHEN v(v_ena)=vena_limit
let tsettle=tcross-tstart
print tsettle

.endc



MODEL

.lib cornerMOSlv.lib mos_tt
.lib cornerRES.lib res typ





