İSTANBUL AIRPORT RNAV (GNSS) STAR RWY 16R/17L/18

Туре	Fix identifier (Waypoint name)	Latitude	Longitude
FlyBy	AYTEK	41:48:29.00N	026:21:42.00E
FlyBy	FM166	41:27:49.58N	028:17:24.99E
FlyBy	FM319	41:45:01.88N	026:34:18.61E
FlyBy	FM320	41:38:08.03N	026:48:13.46E
FlyBy	FM321	41:28:04.74N	026:50:24.39E
FlyBy	FM322	41:26:42.71N	027:06:04.89E
FlyBy	FM801	41:36:43.83N	028:01:14.62E
FlyBy	FM802	41:31:14.64N	028:01:16.08E
FlyBy	FM803	41:25:56.94N	028:03:10.70E
FlyBy	FM804	41:21:12.27N	028:06:50.27E
FlyBy	FM805	41:17:19.92N	028:11:59.61E
FlyBy	FM806	41:22:53.58N	028:17:38.77E
FlyBy	FM807	41:28:26.95N	028:23:18.90E

Туре	Fix identifier (Waypoint name)	Latitude	Longitude
FlyBy	FM820	41:48:39.02N	027:07:09.68E
FlyBy	FM852	41:41:33.27N	027:13:43.33E
FlyBy	FM853	41:34:27.15N	027:20:15.54E
FlyBy	FM854	41:39:35.72N	027:30:13.07E
FlyBy	FM855	41:44:43.41N	027:40:12.17E
FlyBy	FM856	41:47:39.49N	027:47:35.24E
FlyBy	FM857	41:45:36.60N	027:57:55.65E
FlyBy	FM955	41:55:06.47N	028:30:35.74E
FlyBy	FM956	41:53:26.12N	028:12:18.49E
FlyBy	INSTA	41:34:00.03N	028:29:00.01E
FlyBy	IPMIL	41:53:51.37N	026:55:43.67E
FlyBy	RILEX	41:58:16.00N	026:45:59.00E
FlyBy	RIXEN	42:04:56.00N	028:45:58.00E

GENERAL:

If unable to comply the RNAV procedure, inform ISTANBUL CONTROL/YESILKOY APPROACH on initial contact. Otherwise, at first contact with YESILKOY APPROACH report only call sign.

All speeds depicted on the STARs are applied for ATC separation purposes and mandatory. The speed restrictions are to be flown as accurately as possible (accurate within 5 KT). Aircraft unable to conform to these speeds shall inform ATC and state what speeds to be used.

CLEARANCE FOR THE INSTRUMENT APPROACH PROCEDURE:

ATC will clear the a/c to the relevant Instrument Approach Procedure (IAP) for the relevant RWY before the Initial Approach Fix (IAF). A sample of ATC instruction is stated below;

"Call sign, Cleared for ILS Approach (or relevant IAP) RWY"

As soon as such an instruction is received, the a/c shall completely follow the cleared IAP (including the P-RNAV transition) for the relevant RWY.

VECTORING:

Aircraft without P-RNAV approval may lose the sequence and be subject to a delaying action. The a/c concerned will be radar vectored to final, or cleared/vectored to a point from where approach can be made.

RADIO FAILURE PROCEDURE:

Squawk 7600.

Before FM857:

If already cleared to 10000 FT continue via filed/cleared STAR. Otherwise MAINTAIN last assigned level for 3 minutes, then descent to 10000 FT continue via filed/cleared STAR.

At or after FM857:

Continue via filed/cleared STAR by adhering to published profile until INSTA (IAF). Then execute the relevant instrument approach procedure (IAP) for RWY16R and land.

If available call telephone number 0090 212 465 01 21

AIRAC AMDT 05/25 DHMİ - ANKARA