







Work Order - Outbound Warehouse TIMIKA

WO Number

IBS-WHO-TIM-ASM-01-2022-00051

Request Date

19 Januari 2022

Sub Region Site ID ASMAT PAP7149_SERAMIT

| Material Code | Material Name | Description | P (r | n) Diameter | Qty | Total CBM | Total Weight | QC Acceptence | | Note |
|---------------|-----------------|---------------------------|------|-------------|-----|-------------|--------------|---------------|--------|------|
| (Barcode) | iviateriai Name | Description | - 10 | ij Diameter | Qty | Total Colvi | (Kg) | ACCEPT | REJECT | |
| | ST08 | Semen Tonasa @50kg / sak | 600 | 400 100 | 156 | | 24336 | | | |
| | BKS-PV-R-1 | Kolom Panel Surya (L) | 3,2 | 5 Ø13 | 48 | | | | | |
| | BKS-PV-R-2 | Kolom Panel Surya (S) | 1,0 | 3 Ø10 | 126 | | | | | |
| | BKS-PV-R-3 | Kolom Panel Surya (SPA) 📞 | 0,3 | 0 Ø8 | 48 | | | | | |
| | BKS-PV-R-4 | Footplate Panel Surya (L) | 1,1 | 0 Ø13 | 168 | | | | | |
| | BKS-PV-R-5 | Pad (L x) | 2,5 | 1 Ø10 | 104 | | | | | |
| | BKS-PV-R-6 | Pad (L y1) | 3,0 | 1 Ø10 | 58 | 1 | | | | |
| | BKS-PV-R-7 | Pad (L y2) | 1,6 | 1 Ø10 | 58 | | | | | |
| | BKS-PV-R-8 | Tangga (L x-b) | | 6 Ø10 | 12 | | | | | |
| | BKS-PV-R-9 | Tangga (L y-b) | 0,9 | 8 Ø10 | 14 | | | | | |
| | BKS-PV-R-10 | Tangga (L-x) | 2, | g Ø10 | 32 | | | | | |
| | BKS-PV-R-11 | Tangga (L-y) | 0,7 | 8 Ø10 | 50 | | | | | |
| | BKS-PV-R-12 | Anak Tangga (x) | 0,6 | 5 Ø10 | 72 | | | | | |
| | BKS-PV-R-13 | Anak Tangga (y) | 0,7 | 8 Ø10 | 24 | | | | | |
| | BKS-PV-R-14 | Beam (S) | 0,8 | 6 Ø8 | 128 | | | | | |
| | BKS-PV-R-15 | Beam 1 (L-1) V | 3,0 | | 18 | | | | | |
| | BKS-PV-R-16 | Beam 1 (L-2) | 1,6 | 0 Ø13 | 18 | | | | | |
| | BKS-PV-R-17 | Beam 1 (L-3) | 3,0 | 0 Ø10 | 6 | | | | | |
| | BKS-PV-R-18 | Beam 1 (L-4) | 1,6 | 0 Ø10 | 6 | | | | | |
| | BKS-PV-R-19 | Beam 2 (L-1) | 2,5 | 0 Ø13 | 24 | | | | | |
| | BKS-PV-R-20 | Beam 2 (L-2) ✓ | 2,5 | 0 Ø10 | 8 | | | | | |
| | BKS-PV-R-21 | Beam 3 (L-1) | 1,0 | 5 Ø13 | 18 | | | 1 | | |
| | BKS-PV-R-22 | Beam 3 (L-2) | 1,0 | 0 Ø10 | 6 | | | | | |
| | BKS-PV-R-23 | Sloof (S) | 0,8 | 0 Ø8 | 122 | | | | | |
| | BKS-PV-R-24 | Sloof 1 (L-1) | 3,0 | 00 Ø13 | 18 | | | | | |
| | BKS-PV-R-25 | Sloof 1 (L-2) | 1,6 | 0 Ø13 | 18 | | | | **** | |
| | BKS-PV-R-26 | Sloof 2 (L) | 2,5 | 0 Ø13 | 24 | | | | | |
| | BKS-VSAT-R-1 | Pedestal Vsat (L) | 2,4 | 0 Ø10 | 8 | | | | | |
| | BKS-VSAT-R-2 | Footplate Vsat (L) | 0,9 | 9 Ø10 | 24 | | | | | |
| | BKS-VSAT-R-3 | Pedestal Vsat (S) | 1,4 | 7 Ø8 | 15 | | | | | |
| | BKS-VSAT-R-4 | Pedestal Vsat (SPA) | 0,4 | 15 Ø8 | 8 | | | | | |
| | BKS-PG-R-1 | Pedestal Pagar (L) | 0, | 70 Ø10 | 96 | | | | | |
| | BKS-PG-R-2 | Pedestal Pagar (S) | 0, | 71 Ø8 | 120 | | | | | |
| | BKS-PG-R-3 | Sloof (L1) | 2, | 70 Ø8 | 24 | | | | | |
| | BKS-PG-R-4 | Sloof (L2) | 2, | 60 Ø8 | 64 | | | | | |
| | BKS-PG-R-5 | Sloof (L3) | 2, | 20 Ø8 | 4 | | | | | |
| | BKS-PG-R-6 | Sloof (S) | 0, | 3 Ø6 | 373 | | | | | |
| | BKS-PG-R-7 | Footplate (L) | 0, | 33 Ø10 | 480 | | | | | |
| | BKS-BK-R-1 | sengk bak kontrol | 2, | 10 Ø10 | 4 | | 9 | | | |
| | BKS-BK-R-2 | long bak kontrol | | | 12 | | | | | |
| | BKS-TW-R-1 | Pedestal (L) | | | 24 | | | | | |
| | BKS-TW-R-2 | Pedestal (S-1) | | | 4 | | | | | |
| | BKS-TW-R-3 | Pedestal (S-2) | _ | | 16 | | | | | |
| | BKS-TW-R-4 | Pedestal (SPA) | _ | | 8 | | | | | |
| | BKS-TW-R-5 | Footplat (L) | - | | 44 | | | | | |
| | BKS-TW-R-6 | Spacer v | _ | | 4 | | | | 1 | |
| | BKS-SL-R-1 | Pedestal (L) | _ | | 48 | | | 30 | | |
| | BKS-SL-R-2 | Pedestal (S-1) | - | | 28 | | | | | |
| | BKS-SL-R-3 | Pedestal (S-2) | | 40 Ø10 | 96 | | | | | |
| | BKS-SL-R-4 | Pedestal (SPA) | | 42 Ø10 | 16 | | | | | |
| | BKS-SL-R-5 | Footplat (L) | 7 | 34 Ø13 | 176 | 1 | | | | |
| | | | 1 | | 16 | 1 | | | | |
| | BKS-SL-R-6 | Spacer | 0,8 | 36 Ø13 | 16 | | | | | |

Dibuat Oleh.

Diketahui Oleh,

TTD

Diketahui Oleh,

(Firman Adi P) Warehouse Spv

(Kamil) Manager Warehouse & Logistik Ahmad Nasution SPV Warehouse SBY





| BERITA ACARA SERAH TERIMA BAR Tanggal 10 Bulan 03 T di bawah ini telah melakukan serah terim | ahun2022 |
|--|--------------------------------|
| : IBS - WHO - TIM - ASM - 01 - | 2022 - 00051 , 00052 |
| : PAP7149 _ Seramit, PAP7150. | . Yahui |
| : IBS Project | |
| 1 Truck CPA 9522 MB |) |
| | |
| : | |
| | |
| :Menginap di site si | |
| n/Kardus Baik_ | Rusak |
| ai Dengan Dokumen Ya | Tidak |
| Bekisting | |
| buat dengan sebenarnya dan untuk di perg | gunakan sebagai mana mestinya. |
| Transporter | Penerima |
| Nama : Febriandi | Nama : |
| Tanggal: 10-03-2022 67 No. HP: 0822 8598 1130 | Tanggal: |
| | Tanggal |

PICKING LIST 20220310/Out/TIM001/0003



DELIVERY TO

Asmat, Papua, Indonesia

DATE:

2022-03-10

REQUEST NUMBER:

IBS-WHO-TIM-ASM-01-2022-00051

Site ID:

PAP7149

Site Name :

SERAMIT

| Product Code | Material Name | Serial Number | UoM | Qty | Remark |
|--------------|---------------|---------------|--------|-----|--------|
| BKS-PV-R-1 | ACCESORIES | - | Pieces | 48 | |
| BKS-PV-R-2 | ACCESORIES | - | Pieces | 126 | * |
| BKS-PV-R-3 | ACCESORIES | e. | Pieces | 48 | |
| BKS-PV-R-4 | ACCESORIES | Α | Pieces | 168 | |
| BKS-PV-R-5 | ACCESORIES | - | Pieces | 104 | |
| BKS-PV-R-6 | ACCESORIES | - | Pieces | 58 | |
| BKS-PV-R-7 | ACCESORIES | - | Pieces | 58 | |
| BKS-PV-R-8 | ACCESORIES | | Pieces | 12 | |
| BKS-PV-R-9 | ACCESORIES | - • | Pieces | 14 | |
| BKS-PV-R-10 | ACCESORIES | - | Pieces | 32 | |
| BKS-PV-R-11 | ACCESORIES | - | Pieces | 50 | |
| BKS-PV-R-12 | ACCESORIES | - | Pieces | 72 | |
| BKS-PV-R-13 | ACCESORIES | - | Pieces | 24 | |
| BKS-PV-R-14 | ACCESORIES | - | Pieces | 128 | |
| BKS-PV-R-15 | ACCESORIES | - | Pieces | 18 | |
| BKS-PV-R-16 | ACCESORIES | - | Pieces | 18 | |
| BKS-PV-R-17 | ACCESORIES | - | Pieces | 6 | |
| BKS-PV-R-18 | ACCESORIES | - | Pieces | 6 | |
| BKS-PV-R-19 | ACCESORIES | - | Pieces | 24 | 19. |
| BKS-PV-R-20 | ACCESORIES | - | Pieces | 8 | |
| BKS-PV-R-21 | ACCESORIES | - | Pieces | 18 | |
| BKS-PV-R-22 | ACCESORIES | - | Pieces | 6 | |
| BKS-PV-R-23 | ACCESORIES | - | Pieces | 122 | |
| BKS-PV-R-24 | ACCESORIES | - | Pieces | 18 | |
| BKS-PV-R-25 | ACCESORIES | | Pieces | 18 | 1 |
| BKS-PV-R-26 | ACCESORIES | - | Pieces | 24 | 1 |
| BKS-VSAT-R-1 | ACCESORIES | - | Pieces | 8 | |
| BKS-VSAT-R-2 | ACCESORIES | - | Pieces | 24 | |
| BKS-VSAT-R-3 | ACCESORIES | - | Pieces | 15 | i e |
| BKS-VSAT-R-4 | ACCESORIES | , | Pieces | 8 | 3 |
| BKS-PG-R-1 | ACCESORIES | - | Pieces | 96 | |
| BKS-PG-R-2 | ACCESORIES | - | Pieces | 120 | |
| BKS-PG-R-3 | ACCESORIES | - | Pieces | 24 | |
| BKS-PG-R-4 | ACCESORIES | - | Pieces | 64 | |
| BKS-PG-R-5 | ACCESORIES | - | Pieces | 4 | |
| BKS-PG-R-6 | ACCESORIES | - | Pieces | 373 | 3 |
| BKS-PG-R-7 | ACCESORIES | - | Pieces | 480 | |
| BKS-BK-R-1 | ACCESORIES | - | Pieces | 4 | 1 |
| BKS-BK-R-2 | ACCESORIES | - | Pieces | 12 | 2 |
| BKS-TW-R-1 | ACCESORIES | - | Pieces | 24 | 1 |
| BKS-TW-R-2 | ACCESORIES | - | Pieces | 4 | |
| BKS-TW-R-3 | ACCESORIES | - | Pieces | 16 | |

| BKS-TW-R-4 | ACCESORIES | | Pieces | 8 | |
|------------|------------|-----|--------|-----|--|
| BKS-TW-R-5 | ACCESORIES | - | Pieces | 44 | |
| BKS-TW-R-6 | ACCESORIES | - | Pieces | 4 | |
| BKS-SL-R-1 | ACCESORIES | - | Pieces | 48 | |
| BKS-SL-R-2 | ACCESORIES | - | Pieces | 28 | |
| BKS-SL-R-3 | ACCESORIES | - | Pieces | 96 | |
| BKS-SL-R-4 | ACCESORIES | - | Pieces | 16 | |
| BKS-SL-R-5 | ACCESORIES | - | Pieces | 176 | |
| BKS-SL-R-6 | ACCESORIES | - , | Pieces | 16 | |

| Picker | Admin | Pic Gudang |
|-----------------|-----------------|-----------------|
| AW) | The | EMANS |
| JULID . C. TITA | James Kontakins | NATALIA MAINIMU |





DELIVERY NOTE

PT Infrastruktur Bisnis Sejahtera (IBS)
Jayapura, Entrop, Jayapura Sel., Kota Jayapura, Papua 99221

Project Name: BAKTI

Project Name: BAKTI

Site ID: PAP7149
Site Name: SERAMIT
Address: ASMAT, PAPUA, INDONESIA

Order Number: 20220310/Out/TiM001/0003
Request Number: 1BS-WHO-TIM-ASM-01-2022-00051
Order Date: 2022-03-10
Delivery Date:

WO No: IBS-WHO-TIM-ASM-01-2022-00051

Site WBS:MOT: CDD BAK
Vendor: BOPI

| NO | PRODUCT CODE | MATERIAL NAME | UOM | QTY | REMARK |
|----|--------------|---------------|--------|-----|--------|
| L | BKS-PV-R-1 | ACCESORIES | Pieces | 48 | |
| 2 | BKS-PV-R-2 | ACCESORIES | Pieces | 126 | |
| 3 | BKS-PV-R-3 | ACCESORIES | Pieces | 48 | |
| 4 | BKS-PV-R-4 | ACCESORIES | Pieces | 168 | |
| 5 | BKS-PV-R-5 | ACCESORIES | Pieces | 104 | |
| 5 | BKS-PV-R-6 | ACCESORIES | Pieces | 58 | |
| 7 | BKS-PV-R-7 | ACCESORIES | Pieces | 58 | |
| 8 | BKS-PV-R-8 | ACCESORIES | Pieces | 12 | |
| 9 | BKS-PV-R-9 | ACCESORIES | Pieces | 14 | |
| 10 | BKS-PV-R-10 | ACCESORIES | Pieces | 32 | |
| 11 | BKS-PV-R-11 | ACCESORIES | Pieces | 50 | 12 |
| 12 | BKS-PV-R-12 | ACCESORIES | Pieces | 72 | |
| 13 | BKS-PV-R-13 | ACCESORIES | Pieces | 24 | |
| 14 | BKS-PV-R-14 | ACCESORIES | Pieces | 128 | |
| 15 | BKS-PV-R-15 | ACCESORIES | Pieces | 18 | |
| 16 | BKS-PV-R-16 | ACCESORIES | Pieces | 18 | |
| 17 | BKS-PV-R-17 | ACCESORIES | Pieces | 6 | |
| 18 | BKS-PV-R-18 | ACCESORIES | Pieces | 6 | |
| 19 | BKS-PV-R-19 | ACCESORIES | Pieces | 24 | |
| 20 | BKS-PV-R-20 | ACCESORIES | Pieces | 8 | |
| 21 | BKS-PV-R-21 | ACCESORIES | Pieces | 18 | |
| 22 | BKS-PV-R-22 | ACCESORIES | Pieces | 6 | |
| 23 | BKS-PV-R-23 | ACCESORIES | Pieces | 122 | |
| 24 | BKS-PV-R-24 | ACCESORIES | Pieces | 18 | |
| 25 | BKS-PV-R-25 | ACCESORIES | Pieces | 18 | |
| 26 | BKS-PV-R-26 | ACCESORIES | Pieces | 24 | |
| 27 | BKS-VSAT-R-1 | ACCESORIES | Pieces | 8 | |
| 28 | BKS-VSAT-R-2 | ACCESORIES | Pieces | 24 | |
| 29 | BKS-VSAT-R-3 | ACCESORIES | Pieces | 15 | |
| 30 | BKS-VSAT-R-4 | ACCESORIES | Pieces | 8 | |
| 31 | BKS-PG-R-1 | ACCESORIES | Pieces | 96 | |
| 32 | BKS-PG-R-2 | ACCESORIES | Pieces | 120 | 1 |
| 33 | BKS-PG-R-3 | ACCESORIES | Pieces | .24 | |
| 34 | BKS-PG-R-4 | ACCESORIES | Pieces | 64 | |
| 35 | BKS-PG-R-5 | ACCESORIES | Pieces | 4 | |
| 36 | BKS-PG-R-6 | ACCESORIES | Pieces | 373 | |
| 37 | BKS-PG-R-7 | ACCESORIES | Pieces | 480 | |
| 38 | BKS-BK-R-1 | ACCESORIES | Pieces | 4 | |
| 39 | BKS-BK-R-2 | ACCESORIES | Pieces | 12 | |
| 40 | BKS-TW-R-1 | ACCESORIES | Pieces | 24 | |

| NO | PRODUCT CODE | MATERIAL NAME | иом | QTY | REMARK |
|----|--------------|---------------|--------|-----|--------|
| 41 | BKS-TW-R-2 | ACCESORIES | Pieces | 4 | |
| 42 | BKS-TW-R-3 | ACCESORIES | Pieces | 16 | |
| 43 | BKS-TW-R-4 | ACCESORIES | Pieces | 8 | |
| 44 | BKS-TW-R-5 | ACCESORIES | Pieces | 44 | |
| 45 | BKS-TW-R-6 | ACCESORIES | Pieces | 4 | |
| 46 | BKS-SL-R-1 | ACCESORIES | Pieces | 48 | |
| 47 | BKS-SL-R-2 | ACCESORIES | Pieces | 28 | |
| 48 | BKS-SL-R-3 | ACCESORIES | Pieces | 96 | |
| 49 | BKS-SL-R-4 | ACCESORIES | Pieces | 16 | |
| 50 | BKS-SL-R-5 | ACCESORIES | Pieces | 176 | |
| 51 | BKS-SL-R-6 | ACCESORIES | Pieces | 16 | |

| Checker | Receiver | Driver | Supervisor |
|--|------------------------------------|--|--|
| AMIZ | | Tru | to 603-22 |
| Full Name: JULIO C TITA Company: TEMANS Date: 10 - 03 - 2022 | Full Name : Company : Date : | Full Name : RUDI Company : Date : [O - 03-2022 | Full Name: HATALTA MAITIMO Company: TEMANS Date: 10 -03 - 2022 |