

worn surface of the flat [μm]

0
-1
-2
-3
-4

-0.4

-0.2

0

0.2

0.4

x [mm]

— measured
— level set
× mesh motion

cycles

1000

5000

10000

18000

