5
1
2
+4
MI

Ground station
Admin · 14 members

Files 2 to approve 48
Summary rebuilt 2 h ago
Issues 1 on your docs 3

PINNED
general

CONVERSATIONS
power-budget
Ops + vendors 1
antenna-mount
My AI chat 13:20
Petr, Jana Whisper
site-survey Mon
PSU vendor review 28 Oct
6 older

#power-budget
Ground station · Winter-case power margins for the outdoor cabinet

214 earlier messages are summarized for Claude Show summary

Tomáš Král 13:12
New cabinet layout is up. Fan and heater now share the auxiliary rail, so the winter numbers need another look.

cabinet-layout-r4.pdf
PDF · 1.2 MB

👍 3

TODAY · 3 NOV

Jana Dvořáková 13:58
Vendor confirmed the enclosure heater: 40 W, and they want it running continuously below −10 °C. Do we still have margin in the winter case?

Petr Novák 14:01
@Claude what does the power budget leave us at −20 °C with that heater?

Claude AI 14:01 · replying to Petr · read 3 documents

At −20 °C you have **15 W of margin** on the 24 V auxiliary rail, about 8 %. The budget allows 186 W on that rail[1], and the worst-case load with the heater running continuously is 171 W[1, 2].

One thing doesn't add up: the PSU spec rates the auxiliary output at 12 V and 150 W[3]. If that is current, the winter case is 21 W over the rail limit.

Two documents disagree on the auxiliary rail

Power budget v3 §4.2 fresh	PSU spec rev C §2.1 outdated
`Aux rail: 24 V, 186 W max (−20 °C case)`	`AUX output: 12 V DC, 12.5 A (150 W)`
Maintained by Petr Novák	Maintained by Tomáš Král

PSU spec rev C changed in Drive at 11:20 and Hub's copy is still updating, so the new revision may already resolve this.

Message #power-budget

Claude can read 48 documents in Ground station

Send Ask AI