Calibration Method
Kalibrieranweisung

Refer to calibration method and calibration instructions below.

Relative Humidity
Relative Luftfeuchte

15 - 80 %

Ambient Temperature
Umgebungstemperatur

23 ± 3 °C

Working standards used (having a significant effect on the accuracy)
Verwendete Gebrauchsnormale (mit signifikantem Einfluss auf die Genauigkeit)

Item	Type	Serial No.	Calibration Certificate No.	Cal. Due
GG XSRB RUBIDIUM-OSZILLATOR	XSRB	314725/009	RN210742	2022-05-05
34401A MULTIMETER	34401A	US36128743	1-14245602305-1	2023-03-30
5522A CALIBRATOR	5522A	3737902	1-13247405084-1	2021-09-29

Notes
Anmerkungen

Ancillary Functional Measurements:
The calibration procedure include ancillary functional measurements thataffect the traceability or measurement uncertainty of the calibration results. These functional measurement results are marked with an alphabetic character and are not intended to be used in support of the further dissemination of metrological traceability.

Comments on Measurement Results:
The measurement results in the test report stated below have been testedfor compliance with the given specifications and marked if necessary. The associated uncertainty of measurement has been taken into Measurement results that are not covered by the NATA accreditation are marked with 1.

UGB:
Uncertainty Guard Band - Measurement uncertainty violates the datasheet limit.

UGB1:
A compliance statement may be possible where a confidence level of less than 95 % is acceptable.
Die Bestätigung der Konformität ist möglich, sofern ein Grad des Vertrauens von weniger als 95% akzeptabel ist.

UGB2:
A non-compliance statement may be possible where a confidence level of less than 95 % is acceptable.
Die Bestätigung der Nicht-Konformität ist möglich, sofern ein Grad des Vertrauens von weniger als 95% akzeptabel ist.

Conformity statements take the measurement uncertainties into account.
Die Konformitätsaussagen berücksichtigen die Messunsicherheiten.

Ref: ILAC-G8:03/2009 'Guidelines on the Reporting of Compliance with Specification'

Calibration Method:
The instrument was tested in accordance with the relevant manual for Oscilloscope RTH1004, of Rohde & Schwarz and the in-house methods: RF-Z2, RF-Z51, DCVRES-2, FEC-001 contained in the Quality Assurance Manual.

Calibration Instructions:
The calibration of the instrument can be classified as a direct measurement. DC performance was tested by applying known voltages to instrument. Bandwidth was measured with a power standard. Frequency accuracy was measured with a frequency counter synchronized to a rubidium reference. The traceability is represented in the table Working Standards used.