Title Project : Delocalisation industrielle

Created by: trhgtg thtrhrt

Type : Correction

Departement : D. Indus

Probability Scale

Relative conce	Probability of occurrence	
0.0	0.15	0.1
0.16	0.25	0.3
0.26	0.5	0.5
0.56	0.75	0.7
0.76	0.9	0.9

Estimation of Impact

	Impact : IP	Impact : IC	Impact : ID	Impact : IE
E1	7	7	3	1
E2	9	7	6	1
E3	7	6	6	1
E4	6	6	4	5
E5	7	5	2	9
E6	7	7	7	8

Les Matrices AHP

E1

	F1	F2	F3	F4
F1	1.0	4.0	4.0	4.0
F2	0.25	1.0	0.5	0.125
F3	0.25	2.0	1.0	0.14285714285
F4	0.25	8.0	7.0000000035	1.0

E2

	F1	F2	F3	F4	
F1	1.0	3.0	0.25	0.5	

	F1	F2	F3	F4	
F2	0.3333333333333333	333333333 1.0		0.14285714285	
F3	4.0	9.00000090000009	1.0	2.0	
F4	2.0	7.0000000035	0.5	1.0	

E3

	F1	F2	F3	F4
F1	1.0	4.0	0.33333	2.0
F2	0.25	1.0	0.125	0.5
F3	3.000030000300003	8.0	1.0	7.0
F4	0.5	2.0	0.14285714285714285	1.0

E4

	F1	F2	F3	F4
F1	1.0	2.0	4.0	7.0
F2	0.5	1.0	3.0	5.0
F3	0.25	0.333333333333333	1.0	2.0
F4	0.14285714285714285	0.2	0.5	1.0

E5

	F1	F2	F3	F4
F1	1.0	6.0	8.0	2.0
F2		1.0	3.0	0.33333
	0.1666666666666666			
F3	0.125		1.0	0.1666666666666
		0.333333333333333		
F4	0.5			1.0
		3.000030000300003	6.00000000000024	

E6

	F1	F2	F3	F4
F1	1.0	0.33333	3.0	4.0
F2	3.000030000300003	1.0	5.0	7.0
F3	0.333333333333333	0.2	1.0	2.0
F4	0.25	0.14285714285714285	0.5	1.0

Calculation of the risk factor concentration for each undesirable event

Undesirable event	Linked risk factor category	Factors of category	Weighting:Yi	Xi*Yi	Fraction of total Eq	Probability of Occurence	Max Impact	Level of Risk
E1	F1	7	4.0	28.0				
	F4	7	2.0	14.0				
			Sub-Total E1	42.0	0.22340426	0.3	7.0	2.1000001
E2	F1	7	4.0	28.0				
	F3	3	3.0	9.0				
	F4	7	2.0	14.0				
			Sub-Total E2	51.0	0.2712766	0.5	9.0	4.5
E3	F3	3	3.0	9.0				
			Sub-Total E3	9.0	0.047872342	0.1	7.0	0.7
E4	F4	7	2.0	14.0				
			Sub-Total E4	14.0	0.07446808	0.1	6.0	0.6
E5	F4	7	2.0	14.0				
	F1	7	4.0	28.0				
			Sub-Total E5	42.0	0.22340426	0.3	9.0	2.7
E6	F1	7	4.0	28.0				
	F2	2	1.0	2.0				
			Sub-Total E6	30.0	0.15957446	0.15957446	8.0	1.2765957
			Total	188.0	100 %			

Result:

	Accepted Risks			
Code	Description			
E1	Work-related illness			
E3	Drop in quality			
E4	Inadequate design			
E6	Explosion and fire			

Risks à reduire			
Code	Description		
E2	Drop in productivity		
E5	Pollution		