DEPARTMENT OF MECHANICAL ENGINEERING

20ME002 - MANUFACTURING PROCESSES II THEORY OF METAL CUTTING - QUIZ

Student Name:	HARINATH.S	
Register Number:	LE-01	
Date:	2025-07-30	
Time:	09:57:14	
Duration:	5:05 minutes	
Questions:	20 (Random selection from 75-question	bank)

SCORE: 7/20 (35.0%)

GRADE: F

DETAILED RESULTS

Q.No	Your Answer	Correct Answer	Status
1	Longitudinal plane	Transverse plane	X Wrong
2	Low cutting speeds	Low cutting speeds	✓ Correct
3	Cutting speed is very low	Material is ductile with high	X Wrong
4	Axial plane	Longitudinal plane	X Wrong
5	Tool face	Base of tool	X Wrong
6	Increase cutting speed	Control chip formation	X Wrong
7	Ferrous materials	Non-ferrous materials	X Wrong
8	Along the feed direction	Radially inward	✗ Wrong
9	Relationship between forces an	Relationship between forces an	✓ Correct

10	Uncut chip thickness / Cut chi	Cut chip thickness / Uncut chi	✗ Wrong
11	All of the above	All of the above	✓ Correct
12	Difference between rake and cl	Sum of rake and clearance angl	X Wrong
13	Large nose radius	Zero nose radius	X Wrong
14	Both surface finish and tool s	Both surface finish and tool s	✓ Correct
15	400°C	600°C	X Wrong
16	Equal to cutting force	Smallest among all forces	X Wrong
17	All of the above	All of the above	✓ Correct
18	Chip flow angle equals inclina	Chip flow angle equals inclina	✓ Correct
19	Has no effect on cutting force	Decreases cutting forces	X Wrong
20	Both rake angle and friction a	Both rake angle and friction a	✓ Correct

This is an auto-generated report from random question selection.

Generated on: 2025-07-30 09:57:14