## **DEPARTMENT OF MECHANICAL ENGINEERING**

## 20ME002 - MANUFACTURING PROCESSES II THEORY OF METAL CUTTING - QUIZ

Student Name:	sai saran s c	
Register Number:	lat07	
Date:	2025-07-30	
Time:	09:58:20	
Duration:	4:28 minutes	
Questions:	20 (Random selection from 75-question	bank)

SCORE: 8/20 (40.0%)

**GRADE:** F

## **DETAILED RESULTS**

Q.No	Your Answer	Correct Answer	Status
1	High rake angles	Low cutting speeds	<b>X</b> Wrong
2	Difference between 90° and sum	Difference between 90° and sum	✓ Correct
3	Better surface finish	Poor surface finish	<b>X</b> Wrong
4	Maximum at the shear plane	Maximum at the shear plane	✓ Correct
5	Surface finish only	Both surface finish and tool s	<b>X</b> Wrong
6	All of the above	All of the above	✓ Correct
7	Thermal effects	Shear stress exceeding yield s	<b>X</b> Wrong
8	All of the above	All of the above	✓ Correct
9	Angle between cutting edge and	Angle between shear plane and	<b>✗</b> Wrong

10	Dry cutting	Mist cooling	✗ Wrong
11	Equal to normal rake angle	Less than normal rake angle	<b>✗</b> Wrong
12	Chip width / Cut width	Cut chip thickness / Uncut chi	<b>✗</b> Wrong
13	Energy per unit volume of mate	Energy per unit volume of mate	✓ Correct
14	All of the above	All of the above	✓ Correct
15	At 45° to the direction of cut	Perpendicular to the direction	<b>✗</b> Wrong
16	Cutting temperature	Cutting forces	<b>✗</b> Wrong
17	Flank face and cutting edge	Tool face and reference plane	<b>✗</b> Wrong
18	Zero nose radius	Zero nose radius	✓ Correct
19	All of the above	All of the above	✓ Correct
20	Depth of cut	Feed rate	<b>✗</b> Wrong

This is an auto-generated report from random question selection.

Generated on: 2025-07-30 09:58:20